

Line Work Processing

AgSafe Safe Work Procedure

Awkward Machine Controls

Hazard

Controls may be difficult to manipulate and/or improperly located. This may cause ergonomic stress on the hands, arms, shoulders, and upper back, and may result in injury.

Possible Solutions

1. Use gloves to pad the hands
2. Locate controls for ease of use
3. Maintain controls to ensure ease of operation

Falls and Caught by Machinery

Hazard

Frequent and rapid movement near heavy machinery increases the chance that employees may slip into the machine or be caught by or between moving parts. This is especially true if machinery is outside or exposed to wet or icy conditions.

Possible Solutions

1. Follow good housekeeping procedures
2. Properly guard machinery to keep employees away from moving parts
3. Install guardrails around dangerous equipment to prevent injury

Please use the following **Safe Work Procedures** as a guideline to building your own safe work procedures.