Corn Harvester

AgSafe Safe Work Procedure

- 1. Install the manufacturer's guarding plus any other guarding on tractor mounted units
- 2. Reduce the chances of plugging and associated injury by maintaining proper ground speed
- 3. Adjust the snapping rolls and gathering chains for good stock feeding
- 4. Disengage the power and shut off the engine before dismounting or attempting any service or unplugging
- 5. Material feeds faster than you can let go ensure all power sources are eliminated prior to unplugging
- 6. Never turn too sharply especially on hillsides
- 7. Never stand while operating the corn harvester
- 8. Keep steps and platforms clear
- 9. Prevent fires by using a radiator screen. Shield manifold and muffler from leaves and other flammable materials
- 10. Provide a fire extinguisher on the equipment

Please use the following **Safe Work Procedures** as a guideline to building your own safe work procedures.

